

|) | Dual on night take-offs and landings | COURT OF INQUIRY, INVESTIGATING OFFICER'S REPORT: | CER | - |
|---|---|---|------------------|---------|
|) | Engine sputtered and failed at 300 ft. after take-off at night. This wa | | D-14 |))· |
|) | the 11th takeoff during the night th had made. Pilot turned back and made successful downwind landing | · | |) |
|) | on a erodrome. | RECOMMENDATIONS: | • |)) |
|) | PRIMARY CAUSE: Engine failure. | | |) |
|) | | | |) |
|) | | ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) (NIL. | THER |) |
| } | | | |) |
|) | SECONDARY CAUSE OR CONTRIBUTING FACTORS: | | |) |
|) | | | RECORDED BY DATE |) |
| Ć | R.C.A.F. FORM L20 REG. 1247 10M-15-11-41 | e e | CHECKED BY DATE |)) |
|) | |))))))))) | |) |