

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	
Starting aircraft.	OR COMMANDING OFFICER'S REPORT:	
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: D-14	
Mechanic failed to clear propellor on contact and was struck by same.	COMPOSITION:	
PRIMARY CAUSE:	RECOMMENDATIONS: Constant instructions on propellor swinging and precautions to be taken.	
56. Propellor swinging.		
	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER NiL.	
SECONDARY CAUSE OR CONTRIBUTING FACTORS: Carelessness on part of mechanic and slippery ground due to ice	RECORDED BY DATE	<u>-</u>
and slippery ground due to ice.	RECORDED BY DATE CHECKED BY DATE	