

/>>>>> >	
Proceeding to solo cross country.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: D-14
) NATURE OF ACCIDENT AND STAGE OF FLIGHT: Before starting engine the pilot and mechanic exchanged the usual	DATE: COMPOSITION:
signals. On starting the propellor struck the mechanic, injured him and broke the propellor blade.	RECOMMENDATIONS:
) PRIMARY CAUSE:	7
56. Propellor swinging.	
)	ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other
))	Airman placed on charge and log book endorsed and logged.
) SECONDARY CAUSE OR CONTRIBUTING FACTORS:) ,
24. Carelessness.	RECORDED BY DATE
R.C.A.F. FORM L20 REQ. 1247 10M—15-11-41	CHECKED BY DATE