

,	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
Routine daytime solo practice.	TECHNICAL OFFICER'S REPORT: Very small piece of lining missing or very small pie-
) NATURE OF ACCIDENT:	ce of dirt may have been lying in the well under the needle valve and when the A/C was in an inverted pos-
Engine cut out while practicing a	ition, it became dislodged and caught between the nee-
slow roll. Force landing carried out.	FINDINGS: SUMMARY No.
	dle valve and its seat, allowing the carburettor to
)	flood.
))
))
)	
))
CLASSIFICATION:)
54. Engine failure in the air.)
,)
))
SECONDARY OR CONTRIBUTORY FACTORS:)
)	ACTION TAKEN:
	NiL.
R. C. A. F. L 20 (Revised)) 7M-4-43 (3202) K. P. 5051) i
H. Q. 885-L 20	C. C. LTD. 7084-43
[////// //////////////////////////////	