

	The second secon	
/	))) <b>))))))</b> ))))))))	see . se
) PURPOSE OF FLIGHT:	TECHNICAL OFFICER'S REPORT:	
Routine instructional flight.	From external visual examination it has been ascer-	
	tained that ignition has gone out of time, which mus	ત
NATURE OF ACCIDENT:	have been caused by shearing of pin or key within	)
) Sgt. Owen was demonstrating rolls to	motor but which is impossible to determine without dismantling.	)
) his pupil at correct height and in th	COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:	
flying area. From one of rolls, the	FINDINGS: SUMMARY No.	)
engine failed to pick up, and so he		)
made a correct and successful forced		
landing. Noise of engine suggested		
internal damage.		)
)	·	)
)		~
)		<b>)</b>
)		-/ -
CLASSIFICATION:		)
) 54. Engine failure in the air.		)
)		)
)		,
SECONDARY OR CONTRIBUTORY FACTORS:		,
,	ACTION TAKEN:	)
)		)
)	NIL	)
R. C. A. F. L 20 (REVISED) ) 7M-4-43 (3202) K. P. 5051		`
H. Q. 885-L 20	C. C. LTD. 7084-43	ノ
) ) { ) ) ) <b>) ) ) ) ) ) ) )</b>	** <b>)))))))))))</b> ))	)