

PURPOSE OF FLIGHT:	TECHNICAL OFFICER'S REPORT:
12-15-22	Spark plug changed
NATURE OF ACCIDENT:	
Engine started to splutter and run	COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:
rough at 2000 ft. so turned back to aerodrome. Engine picked up and ran	FINDINGS: SUMMARY NO.
smooth for a short spell but R.P.M.'s	1
) finally dropped to 1500 when near	
base. Closed throttle and force landed successfully.	
)	
CLASSIFICATION:	
54. engine failure in the air.	
SECONDARY OR CONTRIBUTORY FACTORS:	
33. Technical Defect.	
)	ACTION TAKEN:
I .	Nil
R.C.A.F. L 20 (REVISED) 7M-4-43 (3202) K.P. 5051 H. Q. 885-L 20	C. C. LTD. 7084.43
))))))))))))))))))