

	2222222222222
PURPOSE OF FLIGHT:	TECHNICAL OFFICER'S REPORT: Engine ground run after
) Wireless Exercise.	return to airport, and it was found that excessive oil was being thrown from engine breather. Compression
NATURE OF ACCIDENT:	was good, E gine still under investigation.
) Pilot reported nevs dropping from from 1950 to 1750 and oil pressure at	COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:
20 lbs., so forced landed. On	FINDINGS: SUMMARY No.
) Inspection oil had been lost through breather. Almost 8 quarts of oil were added and a/c was flown back to airpo	
) in 20 minutes and 7 more quarts oil w	
) needed.	
)	
)	, ,
) CLASSIFICATION:	
54.) Engine failure in the air.	
)	
)	
SECONDARY OR CONTRIBUTORY FACTORS:	
) 33. Technical defect.	ACTION TAKEN:
)	Pilot picked good field and carried out successful
R. C. A. F. L 20 (REVISED) 7M-4-43 (3202) K. P. 5051	forced landing.
H. Q. 885-L 20	C. C. LTD. 7084-43
))))))))))))))))))) 	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,