

/			o l
)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER FRIAD PIPC DE PONTES MC) :
)	PRACTICING SEQUENCES.	OR COMMANDING OFFICER'S REPORT:)
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	COMMANDING OFFICER'S REPORT DATE: 3-2-41)
)	FAILURE ENGINE TO RESPOND WHEN THROTTLE	COMPOSITION:	ال ا
)	OPERATED AND MISJUDGMENT OF HEIGHT OWING TO	G/C T.A. LAWRENCE	.)]
)	POOR LIGHTING CONDITIONS ON NEW FALLEN SNOW.	·	5
_		RECOMMENDATIONS:	
)		(1) DISCIPLINARY ACTION, ALREADY TAKEN. (2) ENDORSEMENT OF THE	7
)	PRIMARY CAUSE:	PILOT'S LOG BOOK AS FOLLOWS: "DISOBEDIENCE IN CARRYONG OUT UNAUTHORIZED PRECAUTIONARY FORCED LANDING PRACTICE".	3
)	DISOBEDIENCE OF REGULATIONS IN CARRYING OUT	SIGNET THE THE PROPERTY OF THE	
$\vec{\mathbf{a}}$	UNAUTHORIZED PRECAUTIONARY FORCED LANDING		,,,
3	PRACTICE. A 7 FULLDING A DOMESTIC PRODUCT.	ACTION TAKEN:	` ,
))		(A) DISCIPLINARY (B) TECHNICAL (C) OTHER ALREADY TAKEN.) i
ノ			7
))		·	.): .:
ر د:			.) !
: <u>)</u>	SECONDARY CAUSE OR CONTRIBUTING FACTORS:		;
)	MISUSE OF THROTTLE DURING PRECAUTIONARY FORCED LANDING PRACTICE.	RECORDED BY DATE)
))
:)		CHECKED BY DATE)
))))))))))))))))))))))))))))))))))))))))

.

-