

, ) )	SECONDARY CAUSE OR CONTRIBUTING FACTORS:	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER	)
	PRIMARY CAUSE: The slip stream from R. 7440 caused R. 4013 to turn.	This accident is the result of lack of air sense.  Any pilot who Taxi's immediately behind another aircraft whose engine is running strongly is guilty of carelessness. Log Book entry made "Carelessness; Taxi-ing".  ACTION TAKEN:	3
	DUTY ON WHICH ENGAGED:  Air Tests.  NATURE OF ACCIDENT AND STAGE OF FLIGHT: Taxying behind aircreft R7440 whilst it was being run up by Cpl. Woodburn. Application of brakes caused the aircraft to tip on its nose damaging	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:  Commanding Officers Report.  DATE: 11-2-41  COMPOSITION:  (A. Shekleton) Group Captain.  RECOMMENDATIONS:	<b>3</b>