

DUTY ON WHICH ENGAGED: Carry out steep turns.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING-OFFICER'S REPORT:
- variy our stock turns.	Commanding Officers Report.
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: 24-2-41 LUC/PCDUW/UCDE/ COMPOSITION:
) Failure of the undercarriage	<del></del>
) hyrdraulic system.	(A. Shekleton) Group Captain
)	· · · · · · · · · · · · · · · · · · ·
)	RECOMMENDATIONS:
)	All instructors have been ordered to add as an
additional practice the lowering by mechanical means  PRIMARY CAUSE:  of the undercarriage before first solo. The mechanical	
After failure of the undercarriage device is inefficient and sometimes requires very system, the pupil attempted to lower considerable strength to operate.  The undercarriage by means of the mechanical hand gear. Resistance became great ACTION TAKEN:  and he was unable to rotate the handle any further. Failed to realize the necessity  for reducing airspeed to 90-100 m.p.h. before  lowering undercarriage.	
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
)	)
)	RECORDED BY DATE
)	
	O ( ( ( ( ( ) ) ) ) ) ) ) ) ) ) ) ) ) )