

ı	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
ı	PRACTISING SEQUENCES 6.7.9.10 12,15.16.  17 AND LOOPS.  NATURE OF ACCIDENT AND STAGE OF FLIGHT:  PILOT NECAME LOST ON SOLO PRACTICE FLIGHT,  AND ENGINE FAILED, NECESSITATING FORCED  LANDING IN DEEP SNOW, IN WHICH AIRCRAFT  OVERTURNED.	COMMANDING OFFICER'S REPORT:  COMMANDING OFFICER'S REPORT.  DATE:  COMPOSITION:  F/L E.A. WEAVER.  PE/SAMP/AM/I
	PRIMARY CAUSE:  (1) Possible ICING IN CARBURETTOR. (ENGINE CHECKED LATER AND FOUND SERVICEABLE.)	RECOMMENDATIONS:  "AIRCRAFT ARE TO REMAIN AS CLOST TO MALTON AEROBROME AS THE VOLUME OF AIR TRAFFIC AND THE NATURE OF THE FLYING PERMITS."  (SECTION 40, PAGE 6 OF STATION STANDING ORDERS.)
	(11) LANDING IN DEEP SNOW.	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  (A) ADMONISHED - PROMOTION DEFERRED.
	SECONDARY CAUSE OR CONTRIBUTING FACTORS:  CARELESSNESS ON PART OF PILOT.	RECORDED BY DATE
	))))))))))	CHECKED BY DATE