

) )	DUTY ON WHICH ENGAGED: T exying Bat le R7438	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT: The wheels of the a/c were fixed in fairly thick snow, Pilot opened up the throttle, and on realising the tall had lifted had immediate difficulty in throttling back owing	DATE: Commanding Officers Report.  COMPOSITION: 19-3-41  Wing Commander (D.M. Gordon)  RECOMMENDATIONS:
	to the tight throttle, and the propellor struck the ground.  PRIMARY CAUSE:  Pilot opened up thethrottle and the tail lifted.	Numerous lectures have already been given to all pupils on the necessity for exercising care and common sense.  Pupils have since been warned again that all accidents due to carelessness will be severely nunished.  ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
• •	SECONDARY CAUSE OR CONTRIBUTING FACTORS: The wheels of the a/c were fixed in fairly thick snow.	RECORDED BY DATE
)	) ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) )	O ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) )