

		and the same of th
/		
•	DUTY ON WHICH ENGAGED: Starting up	COURT OF INQUIRY, INVESTIGATING OFFICER
•	engine.	Commanding Officer's Report.
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: 18-3-41
•)	The switches were turned on before	COMPOSITION:
ì	McAlpine swinging airsrew called	Group Captain T.A. Lawrence.
	Contact. The engine started and	<u></u>
)	the propellor struck ACl McAlpine)
)	in the hand.	RECOMMENDATIONS: This case is being investigated
•		further, and if sufficient evidence is availabel
•		disciplinary action will be takken against ACl Birker.
)	PRIMARY CAUSE: Neglect on the part of	
`	the airman in the cockpit ACl Birke	er e
	in failing to ensure the switches	
)	were fully off, after the airman swi	
)	the airsrew had called switches off.	
``		(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
		. , ,
)) į
)		(,
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:	$\mathcal{L}_{\mathcal{L}}$
		· ·
		RECORDED BY DATE
) +
)) i
``		CHECKED BY DATE
	, , , , , , , , , , , , , , , , , , , 	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,