

low flying sequence	J. OR CC	MMANDING OFFICER'S REPO	RT;	
		Commanding Officer	r's Report.	
NATURE OF ACCIDENT AND S		6-3-41		
	ind the instructor COMP	SITION:	•	
flew below power 1:			.E. Manser	
a gyy wire between		Lieut.	·	
breaking the proper caused the motor to		MENDATIONS: Severe	34	
vibration. Motor		Devere	disciplinary warning.	
· c		1Leo/PCL	1- 10011	
PRIMARY CAUSE: Flow to		120/102	12 170-12	
poor judgment in no				
good country clear	of obstacles.			
	ACTIC	N TAKEN:		
		DISCIPLINARY (B) TECHNICAL	L (C) OTHER	
SECONDARY CAUSE OR CONT	RIBUTING FACTORS:			
SECONDARY CAUSE OR CONT	RIBUTING FACTORS:		RECORDED BY DA	