

/))))))))))		,
()	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	
)	FORCED LANDING PRACTICE.	OR COMMANDING OFFICER'S REPORT: COMMANDING OFFICERS REPORT.	
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: 15-3-41)
)	PRACTISING FORCED LANDING AT 2500 FEET.	COMPOSITION)
)	CLEARED ENGINE QUICKLY AT 2000 & 1000 FT.	SQUADRON LEADER (J.L. BERVEN)	,
•	OPENED THROTTLE AS NORMAL AT 200 FT. BUT ENGINE		•
7	FAILED TO RESPOND, CLOSED THROTTLE AND OPENED	RECOMMENDATIONS:	1
)	IF AGAIN BUT ENGINE STILL FAILED TO CATCH. JUST AT THIS TIME WHEELS HIT THE GROUND AND)
)	THE A/C TURNED OVER IN THE DEEP SNOW.	ACCIDENT APPEARS TO BE DUE TO AN ERROR OF JUDGMENT AND INEXPERIENCE OF THE PILOT.)
)	PRIMARY CAUSE:)	,
)	NOT MAINTAINING ENGINE AT SUFFICIENT)
•	TEMPERATURE FOR IT TO RESPOND QUCKLY	,	
Ó	HHEN THROTTLE OPENED.	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
))
Ć	SECONDARY CAUSE OR CONTRIBUTING FACTORS:		,
)	ERROR OF JUDGMENT IN THAT WHEELS HIT THE GROUND),)
)	STICKING IN THE DEEP SNOW AND OVERTURNING A/C	RECORDED BY DATE	
)		CHECKED BY DATE)
))