

PRIMARY CAUSE: Inexperience on the part of the pilot. ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	ted out.
)
)))
SECONDARY CAUSE OR CONTRIBUTING FACTORS: There was a slight drift. RECORDED BY	DATE