

DUTY ON WHICH ENGAGED:

Instrument flying.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Instructor 1st Pilot. After landing the tyre of the starboard wheel burst and the aircraft swung off the runway and tipped forward in soft earth resulting in damage to the aircrew.

PRIMARY CAUSE:

Starboard tyre burst after normal landing.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Aircraft swung off the runway into soft ground and tipped up on nose.

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

Monthly Accident Report

DATE:

COMPOSITION:

LS/UTB

RECOMMENDATIONS:

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

RECORDED BY

DATE

CHECKED BY

DATE