

Night Flying Dual Instruction.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Aircraft landed about one mile short of flare path struck tree an was burned out.	DATE: COMPOSITION: LEM/AOP/ES/FT/M/L/AB/GA
PRIMARY CAUSE: FAILURE OF MERLIN ENGINE DUE TO EXPLOSION IN INDUCTION MANIFOLD OCCASIONED BY FAULTY FLAME TRAPS, WHICH CAUSED ENGINE TO CATOM: FIRE IN THE AIR.	RECOMMENDATIONS: (A) THAT THE FLAME TRAPS INSTALLED IN ALL MERLIN ENGINES BE EXAMINED FORTHWITH. (B) THAT THE ALLOCATION OF AIRCRAFT BE BROUGHT UP TO ESTABLISHMENT TO ALLOW FOR SUCH EXAMINATION. THE AIR OFFICER COMMANDING DOES NOT CONCUR IN THE FINDINGS ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
AIRCRAFT UNDERSHOT, HAVING INSUFFICIENT HEIGHT TO REACH AERODROME, AND IN DOING SO, THE STARBOWING WAS TAKEN OFF ON IMPACT WITH TREE, AND AIRCRAFT DESTROYED.	ARD CHECKED BY DATE