

Ϊ	(3) 3) 3) 3) 3) 3 13 13)
()	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	
)	Practizing Sequences	OR COMMANDING OFFICER'S REPORT: IM /A M 5	1
)	2,4,5,6,7,8, & 9. NATURE OF ACCIDENT AND STAGE OF FLIGHT:	COMPOSITION OF THE COURT.)
)	Aircraft dived into woods. At ABOUT 16:45 HOURS THE A/C WAS SEEN AT ABOUT 2500 DOING A VERTICAL DIVE WHICH CONTINUED	COMPOSITION:)
)	RIGHT INTO THE GROUND. DURING THE DIVE PARTS	FELYING OFFICER C.G. HARVILLE.	j
)	OF THE WINGS GAVE AWAY, AS PLYWOOD FABRIC AND NOSE RIB AND PART OF TRAILING EDGE SECTION	RECOMMENDATIONS:)
)	WERE FOUND UP TO A 1000 YDS. FROM PLACE THE A/C	THE COURT RECOMMENDS THAT ALL TIGER MOTING BOLLS	9
)	PRIMARY CAUSE: HIT THE GROUND.	AT APPROX. THE SAME TIME AS 4345 BE GROUNDED AND) [
)		INSPECTED FOR FABRIC WORK AND GLUEING, AND SLOT HINGE ATTACHMENTS.	Э[
)		HINGE ATTACHMENTS.	o [
		ACTION TAKEN:	3
•		(A) DISCIPLINARY (B) TECHNICAL (C) OTHER	`\ \f
<i>-</i>			,
ر)
ر)
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:		·- · 1
)	THE AIRCRAFT DOVE AT SUFFICIENT SPEED TO	RECORDED BY DA)
)	CAUSE THE WINGS TO DISENTEGRATE.	VECOUPED DI DA	·)
ં)
)		DA CHECKED BY	")))
	ANTOLO - M	THE PARTY OF THE P	