

/))))))))))))))))))))
()	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER)
)		OR COMMANDING OFFICER'S REPORT: SFE/ET/PF/G/I/XFM	
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: Monthly Accident Return.	7
)	Front plug on #2 Cylinder blew out	DATE:	`
•	during dual instruction on sequence.		,
•	Engine continued to function and)
)	aircraft was flown back to aerodrome)
').	and placed unserviceable. Airscrew	RECOMMENDATIONS:	
3	was badly cracked by plug striking	Disciplinary action teen against	` - •
_	propellor. PRIMARY CAUSE:	LAC Cayen, G.A.	·)
•)	Carelessness on the part of the fit	· · · · · · · · · · · · · · · · · · ·	.)
)	LAC Cayen, G.A. who carried out P.30)
)	inspection.		•
•		ACTION TAKEN:	٠ <u>٠</u>
		(A) DISCIPLINARY (B) TECHNICAL (C) OTHER)
ر)
))
))
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:		`
)	Plug blew out of #2 cylinder whilst		<i>'</i>
Ś	aircraft was in flight striking	RECORDED BY DATE	,
,	and causing damage to propellor.		J
J		CHECKED BY DATE	
)))))))))))))		3