

LITY ON WHICH ENGAGED	COURT OF INQUIRY, INVESTIGATING OFFICER	
•	OR COMMANDING OFFICER'S REPORT.	
Forced landing practice.	ILFA/AOP/ES/NK/IL	
ATURE OF ACCIDENT AND STAGE OF FLIGHT:	DAIE:	
Aircraft forced landed and rolled	COMPOSITION:	
into rock pile. While practising a		
FORCED LANDING, THE PUPIL OVERSHOT THE SELECTE	D	
FIELD AND OPENED THE THROTTLE AT 400°. THE ENGINE RESPONDED BUT FAILED ABOUT 6 SECONDS	RECOMMENDATIONS:	
LATER NECESSITATING A FORCED LANDING.		
	ENGINE FAILURE PROBABLY DUE TO THE CARBURETOR LOADING	
RIMARY CAUSE:	UP DURING THE GLIDE. NO BLAME ATTACHED TO PILOT AS	
Engine failure.	HE HAD TAKEN ADEQUATE PRECAUTIONS TO PREVENT EXCESSIVE	
WHEN THROTTLE OPENED AFTER OVERSHOOTING	COOLING WHILE GLIDING.	
FORCED LANDING FIELD.		
	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
	( ) STATE CONTRACT ( ) STATE R	
ECONDARY CAUSE OR CONTRIBUTING FACTORS:		
ND ALIGHTING SURFACE AND AIRCRAFT RAN		
NTO A ROCK PILE.	RECORDED BY DATE	
	CHECKED BY DATE	_