

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Sequence No. 10-17-22.	OR COMMANDING OFFICER'S REPORT: FB/AOP/ES/PW/MI
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:
During practice spin airscrew stopped, forced landing carried ou	COMPOSITION:
out after an attempt to restart	
engine by diving. In landing the a/c hit the one bad spot in the	
field and turned over.	RECOMMENDATIONS:
PRIMARY CAUSE: Airscrew stopped	
during spin.	
	ACTION TAKEN:
	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
Inexperience in part of pilot	
in restarting engine by diving.	RECORDED BY DATE
	· · · · · · · · · · · · · · · · · · ·
))))))))))))))))))))))))))))))))