

/))))))))))))))))))) 	7)
)	DUTY ON WHICH-ENGAGED-TO	and the second
)	OR COMMANDING OFFICER'S REPORT: TEAPPROD MAMS	.,
)	School training (tech) NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE:)
)	Instructor and pupil practicing COMPOSITION:)
)	sequence starting engine in flight at <u>President</u> : S/L D.E. Galloway (C378) 5000 ft. Engine was stopped and in <u>Members</u> : F/L A.J. Vincent (C1056))
)	subsequent dive instructor fulled the P/O C.M. Black (J3476)	
)	aircraft out quite steeply at 1500 faccommendations: causing starboard mainplane to col-)
)	lapse. Pupil parachuted safely to that a limitation be laid down	9 =
)	PRIMARY CAUSE/ground but instructor killed. for Tiger Moth aircraft and that all	o
)	the pilots be impressed with the danger	Ε
<i>)</i>	Pulled out much too steeply from vertical of putting excessive loads.	Э
)	dive.)
)	ACTION TAKEN:	3
`	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
	******	,
)	NUL)
))
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:	1
ì	Probably due to a too rapid pull out	1
	when diving at excessive speed. RECORDED BY DATE	.)
)	mon ariting as evectoria theore.)
)		٠,
)))))) (((((((((((((((• 3