

DUTY ON WHICH ENGAGED:		QUIRY, INVESTIGATING OFFICER ICA POT/XOV	
!ransportation	OR COMMANDING OFFICER'S REPORT:		
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Aircraft being taxied slowly out	DATE:	Monthly Accident Return.	
take-off taxied into unnoticed crash truck at edge of taxi			
stop revolving propeller hit rear of crash truck.	RECOMMENDA	ATIONS:	
PRIMARY CAUSE: Pilot failed to observe crash truck parked near taxi strip.		Pilots to be instructed to use gree caution when taxiing a/c. Obstruct such as crash tender not to be placed on the close to taxi strip.	tion
	ACTION TAKEN (A) DISCIPL	N: LINARY (B) TECHNICAL (C) OTHER	
	¢		
SECONDARY CAUSE OR CONTRIBUTING FACTORS: Poor visibility from pilot's seat			
in Delta a/c on the ground. Failu of ground personnel to assist pilo		RECORDED BY	DATE
in taxiing.		CHECKED BY	DATE