

UTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Solo flying	OR COMMANDING OFFICER'S REPORT:
ATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: Monthly Accident Return.
Aircraft swung while taking off	COMPOSITION: DC PIESS
and collided with stationery	
aircraft No. V 3291	MA/AA
	RECOMMENDATIONS:
IMARY CAUSE:	All pupils lectured by C.F.I. on correct
Pilot failed to correct swing	action to take if an a/c swings & the assess of relying and manipulating
while taking off.	the throttles to keep the a/c straight.
	ACTION TAKEN:
	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
CONDARY CAUSE OR CONTRIBUTING FACTORS:	
Collided with another aircraft	
while trying to manipulate the	RECORDED BY DATE
throttles to stop swing.	
	CHECKED BY DATE