

| PARTS OF THE AIRCRAFT WHEN IT WAS WRECKED ON IMPACT WITH THE GROUND PRIMARY CAUSE: OBSCURE - For some reason, unknown, The pilot lest control and aircraft went into a spin. ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER WIL SECONDARY CAUSE OR CONTRIBUTING FACTORS: Aircraft struck a tree, henhouse, and the ground on coming out of spin at low altitude. | FLYING PRACTICE • Reconnaissance. NATURE OF ACCIDENT AND STAGE OF FLIGHT: AIRERAFT STRUCK GROUND AT STEEP ANGLE AND HIGH SPEED - SLIGHT PROPERTY DAMAGE - A CIVILIAN(MR. W. GRUNDY) WAS INJURED BY | COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: COURT OF INQUIRY DATE: 16-7-41 COMPOSITION: President - S/L Michelson, T.R. Hember - F/L Moore, N.W. Member - P/O Barron, H.J. |
|--|--|--|
| SECONDARY CAUSE OR CONTRIBUTING FACTORS: Aircraft struck a tree, henhouse, and the ground on coming out of RECORDED BY DATE | PRIMARY CAUSE: | NIL |
| | The pilot lest control and airc | ACTION TAKEN: |