

))))))) j j j j j j j j j j j j j	Jooo
DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
DUAL INSTRUCTION	OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:
ATTEMPTING TO START ENGINE BY DIVING	COMPOSITION: President: W/C R.H. Little
AND WING FOLDED BARK.	Members : F/O D.A. Freeze
· · · · · · · · · · · · · · · · · · ·	F/O I.M.S. Brown.
2 · · ·	RECOMMENDATIONS:
	Issuedinstructions that maximum speed of this
PRIMARY GAUSE:	type of aircraft shall not exceed 125 m.p.h.
Pilot was pulling out of a dive	
when left lower main plain colla	need
TOTAL TOTAL TOTAL PARTIE DOLLA	· · · · · · · · · · · · · · · · · · ·
	ACTION TAKEN:
	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
SECONDARY CAUSE OR CONTRIBUTION TO THE	
SECONDARY CAUSE OR CONTRIBUTING FACTORS	
Structural failure of some comp	
of lower left main plain due ba	
to excessive wing loading on rec	overy or
some weak part in the componend	CHECKED BY DATE