

OVERHAUL DATA

DATE	REASON	DONE BY	REQ'N No.	COST	HOURS SINCE NEW	DATE COMPLETED	ALLOTMENT
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							

ACCIDENT RECORD

DATE	CATEGORY	PLACE	TIME	REPORT REFERENCE	DATE	RANK & NAME OF PILOT	NO. IN CREW	DISPOSAL	DATE SERV.
30/5/41	"C15"	Windsor Mills Pk	1040	4EFTS, SA 250	31/5	LAC. C. B. Hodges			
30.7.	"A"	Shut Oak Mang	1730	4EFTS, SA 378	31/7	Lt P. S. Kenning		WRITE-OFF	
3									
4									
5									
6									
7									
8									

B. S. LTD.

AIRCRAFT RECORD CARD

PAT'D 1920

REMARKS

Re Acc 1:- Finch 4461 collided with Finch 4477 when landing eng. installed - Kennew B5 & 1782/6430.
 Re acc 2:- a/c ran into drain while attempting forced landing outside of authorized Sals area.
 Flying Time:- 574.35 hrs (Log Book)

