

	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	,
)	Circuits and landings.	OR COMMANDING OFFICER'S REPORT:	
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	Monthly Accident Return.	
)	Pilot landed on edge of runway,	COMPOSITION: LS/233	
)	and was unable to correct	• •	)
)	resulting swing to left. Aircraft		7
)	ground-looped.	RECOMMENDATIONS:	
)			)
)	PRIMARY CAUSE:		٠.
)	Inexperience of pilot prevented		
•	corrective action for swing to left.		_
)	101 00	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
)		PP was given additional instruction on landings and correction of changes	
, ,		in position while landing.	
( )	SECONDARY CAUSE OR CONTRIBUTING FACTORS:		
١,	Aircraft ground: looped.		
,		RECORDED BY DATE	
,			
		CHECKED BY DATE	-
_ >			)