

```
DUTY ON WHICH ENGAGED:
                                         COURT OF INQUIRY, INVESTIGATING OFFICER
                                         OR COMMANDING OFFICER'S REPORT:
   Mutual instructional flight
                                                         Monthly Accident Return.
  NATURE OF ACCIDENT AND STAGE OF FLIGHT:
                                         DATE:
                                                          FB/AOP/ES/M/M/
 Forced landing rough field. Aircraft COMPOSITION:
  overturned. Upon closing throttle to
  commence a spin the No. 5 cylinder
  blew partially off, due to vibration.
) Pilot landed at normal gliding speed RECOMMENDATIONS:
  but applied excessive brake pressure
  to prevent a/c from hitting fence.
  PRIMARY CAUSE: A/C turned on its back.
  Engine failure .-- counter weights
  and cylinder had smashed through
  crankcase as a result of counter
                                         ACTION TAKEN:
  weight bolt breaking.
                                           (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
   SECONDARY CAUSE OR CONTRIBUTING FACTORS:
   Forced landing, in small rough
                                                                        RECORDED BY
                                                                                            DATE
   field causing aircraft to overturn.
                                                                        CHECKED BY
```