

| <i>'</i> | DUTY ON WHICH ENGAGED: | COURT OF INQUIRY, INVESTIGATING OFFICER |
|----------|---|---|
|) | Training - Cross Country Flight. | OR COMMANDING OFFICER'S REPORT: |
|) | NATURE OF ACCIDENT AND STAGE OF FLIGHT: | Monthly Accident Return. |
|) | Two pupils engaged on Cross Country flight. Port engine seized up due to oil cock being turned off. Successfully landed in field of crop which damaged tips of airscrew | FE/ET/OM/G/Z |
|) | • | |
|) | PRIMARY CAUSE: | |
|) | Port engine failed due to oil cock being turned off. | |
| Ý | | ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER |
|)) | | Disciplinary action taken against N.C.O. i/c of Flight. |
|) | SECONDARY CAUSE OR CONTRIBUTING FACTORS: Airscrew damaged by high crop | |
|) | during forced landing. | RECORDED BY DATE |
| ,) | | CHECKED BY DATE |