

DUTY ON WHICH ENGAGED: COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: SOLO TRAINING. COURT OF INQUIRY NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE: September 22nd, 1941. COMPOSITION: PILOT JUMPED AT TOO LOW AN ALTITUDE. President S/Ldr. S. Volk. Member Lft. Lt. L.N. David. Member G. Menard. RECOMMENDATIONS: Civilian. J.G. Elliott. Include specific orders in all "Forced Landing" Instructions that, "Pupil pilots are forbidden to take off after any forced landing. PRIMARY CAUSE: (I) PUPIL BILOT BECAME LOST. Pilot failed to contact his station by telephone when first forced landed as instructed. ACTION TAKEN: V(II) Abandonment of the aircraft by the (A) DISCIPLINARY (B) TECHNICAL (C) OTHER Pilot when he became lost in the dark, at too low an altitude for Nil the parachute to be effective. SECONDARY CAUSE OR CONTRIBUTING FACTORS: The Pilot struck the ground before his parachute opened and the aircraft RECORDED BY DATE crashed. CHECKED BY DATE