

٦s 81

O١ 11 GΙ 91 41 81 61 SQ 12

(22 (

LZ

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGAT	ING OFFICER	
Practicing sequences 6, 7, 9, 12,		M / ~ T	
NATURE OF ACCIDENT AND STAGE OF FLIGHT:		and the same of th	
Pilot was preparing to park 4637	in COMPOSITION:	TO A/X CG	
line. Mechanic grabbed wing tip		MAIXA	
swinging aircraft around and propellor struck top wing of 4661		MAZXA	
broborror porces out will be 4001	RECOMMENDATIONS:		
	NIL		
PRIMARY CAUSE:			
Error on part of mechanic.			
	ACTION TAKEN: (A) Disciplinary (B) Technic	CAL (C) OTHER	
	MECHANIC WAS DISCHARGED BY		
	·		
SECONDARY CAUSE OR CONTRIBUTING FACTORS:			
110			
COLLISION BETWEEN AIRCRAFT ON GROUND	······································	RECORDED BY	DATE
		CHECKED BY	DATE