

,		
DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	
Flying Training.	OR COMMANDING OFFICER'S REPORT: R 170	
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	,	
Aircraft hit boundary light in	DATE: COMPOSITION: TCO/PCT	
endeavor to avoid mudpatch. Main spar starboard wing crashed.	n	\$
	RECOMMENDATIONS:	
PRIMARY CAUSE:	N:L	
Error of judgment on the part of the pilot due to inexperience.	•	N.
	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
	NIL	
SECONDARY CAUSE OR CONTRIBUTING FACTORS:		
HIT BOUNDARY LIGHT WHILE TAXIING	RECORDED BY	DATE
	CHECKED BY	DATE