

			ì
· ′	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	′
,		OR COMMANDING OFFICER'S REPORT:	
)	Solo flying training practice.	. 170	
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: COMPOSITION:  FOR THE SAME PARTY IN THE SA	)
)	Engine stopping following prolonger	COMPOSITION:	)
)	aerobatics. Undershot chosen forced landing field.		)
<i>,</i> )		RECOMMENDATIONS:	)
)			<b>-</b> )
`	PRIMARY CAUSE:	NIL	`
<i>)</i>			,
)	Error of judgment following low spinning. IN UNAUTHORIZED FLIGHT.		
)	TOW OPERATION IN CONNOTHONIZED TETANIT		)
)		ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER	)
)		28 days detention and pupils flying training has been discontinued.	)
)			)
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:		
)	Undershot forced landing and landed in trees.	RECORDED BY DATE	)
)			)
j		CHECKED BY DATE	)
	$(x,y) \rightarrow (x,y,y) \rightarrow (x,y,y) \rightarrow (x,y,y)$		)_