32 (- 2 0 0 0		Service 1 servic			STANTS GET	105 / C		13 13 14 15 15 15 15 15 15 15 15 15 15 15 15 15	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		15 18 H				3 2 1 5 () 5	(
<u>_</u> ^/	ζ. V	PILOT OTHERS AIRFRAME FAILURE CAUSES OF ACCIDENTS								ENGINE FAILURE					(
in /2	PE OF	UNIT 10 B.R. SQUAD NEWFOUNDLAND	EAC	PLACE AEORDBOME				DATE 11-9-41 TIME 0915 H.O. FILE 1100-7-50				115	3	145 146 16 (1)	(
	Ϋ́	A/C TYPE DIGBY	-	No.	750		CRASH CAT. B		SE	ME X	DA	X	NIGHT	$1 \land 1 \land$	1 / 52 / /	
<u>_</u> ^	\square	NAME	,R:A	NK :	No.	DUTY		IULNI	RIES			SERIC	SERIOUS >		chi aki	
	, H	BUTTS, R.A. Cameron, A.M.	F)/1	ا ا	C854 P UNINJURED FATAL INJUR C996 UNINJURED C988 UNINJURED R71760 UNINJURED CARD SERIAL NO.					F	ATAL.	INJURY	n Z	Outrality = (
(°)/ (°)/ (°)/	OF ENGIN	WILLIAMS, E.M. HUNTINGTON, W.H.	F/1 SG								1 1	oring 5 ((
	YPE	<u> </u>								· · ·	į				14 / " (•
(2/	-	TYPE A/F & ENGINE No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DAT	⋷	ног		ON TYPE		TOTAL			Tribito 1	٠,
(= 1 v		Digey 750	SERIOUS	i-			INST.	NIGHT		SOLO	DUAL		6 MOS.] ⊣	/*e/ \°(C
	\ Y∺	WRIGHT CYC 3027 WRIGHT CYC 3117	SERIOUS SERIOUS						***************************************		/0	36		I G H	(1) Ct. (1) (1) (1)	
	ATEGO		UNIT No. & DA	TE	сом.	No. & C	ATE	REPOR	т.	FII	E	D,	ATE	OF.	ζ, μ, ω (ζ, μ, ω (ω (
(1)			ļ	NATU	JRE	O F	ACCIE							Ш	12 CP2 S N (
(2)	(Z1 ((3 b (S	91	41 81 6	0 00		(t	\n\n\n\n\n\n\n\n\n\n\n\n\n\n\n\n\n\n\n	97 (2 2		06 E 26	

,5			$) \rightarrow) \rightarrow)$)))))
)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICE	<u>ER</u>)
.)	LOCAL FLYING	OR COMMANDING OFFICER'S REPORT: R 170		
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	•	*4)
)	LOCKING DEVICE WAS NOT REMOVED FROM ELEVATORS	DATE: COMPOSITION:	I W)
)	FOR TAKE-OFF. AIRCRAFT FAILED GO LEAVE THE	· · · · · · · · · · · · · · · · · · ·		
)	GROUND AND COULD NOT BE STOPPED BEFORE IT			
)	CROSSED THE DITCH AT THE END OF THE RUNWAY. IT	RECOMMENDATIONS:		· .
`	OF THE RUNMAY, IN SOME BUSHES.			,
)	PRIMARY CAUSE:	NIL		<i>)</i>
)	Negligence of ground crest.			
)				·)
)		ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) O	THER	Š
)		STREAMERS ARE BEING PLACED ON ALL LOCK	S.)
))
))
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:			j.
)	AIRCRAFT WENT OVER DITCH AND INTO BUSHES			
)			RECORDED BY	DATE
,				,
			CHECKED BY	DATE
))))))))))))))))))))))))))