OSO NEW AND	OTHERS	* * * * * * * * * * * * * * * * * * *		SURPLIANTS SELLEN		RHULL OR M		7		S FAIL		
4			A U	SES O		CCIDE	ENTS					
	.F.T.S.	COM.	it	LACE				DATE]		1 TIME 1		1 1 1 / 3
A/C	Mount Hope, Ont. 1			Mount Hope Aerodrome				H.Q. FILE 1100-45-45				M - S WEY
TYPE Finch II			l N	° 4545	5	CAT. C 1		SE X	ME	DAY	NIGHT	[A]O] / a
NAME RA			RANK	No.	DUTY		ענמו	hlES		SERIO	ous	C E Co
Fischette, C.R. L.			LAC	R108609	P.		Uninju			FATAL	INJURY	A U S
[1]												
z o											2.5	
ž L										CAF SÉRIA		S OF
0								*			-	
[[] [] [] [] [] [] [] [] [] [Ţ		<u> </u>	<u> </u>	11 3.5.	. *					
TYPE A/F & ENGINE	No.	EXTENT OF DAMAG	E FO	RT SERIAL M No.	DAT	HOL			ON TYPE TO			S JAH
Finch II	4545	Sligh	t			INST	NIGHT	DUAL S		TOTAL AL SOLO	LAST 6 MOS.	[] → [Kg
							1	1:45 :	3511:	45 : 15		[a / &
Kinner B	5R 6508	Nil					-					371. I Z Z
w	0 0.TE											
SIGNAL NO. & DATE UNIT NO. & DA		DATE	TE COM, No.		ATE REPOR		RI	T FILE		DATE		

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Solo flying training.	OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:
Coming in for normal landing wing	COMPOSITION:
dropped and aircraft nosed over.	
	RECOMMENDATIONS:
PRIMARY CAUSE:	Nil
Overcorrective action of rudder	
caused aircraft to ground loop.	
	ACTION TAKEN.
• • • • • • • • • • • • • • • • • • •	ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other
·	(A) Disciplinary (B) Technical (C) Other
·	
·	(A) Disciplinary (B) Technical (C) Other
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	(A) Disciplinary (B) Technical (C) Other
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	(A) Disciplinary (B) Technical (C) Other More dual.
•	(A) Disciplinary (B) Technical (C) Other