

, , , , , , , , , , , , , , , , , , ,		, , , , , , , , , , , , , , , , , , ,	, , , , ,
outy on which engaged: Solo flight	COURT OF INQUIRY, INVESTIGATING OFFIC	<u> </u>	
2010 IIIGHC	OR COMMANDING OFFICER'S REPORT:		
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	RI70		
VALUE OF ACCIDENT AND STAGE OF FEIGHT.	COMPOSITION:	んだんしょ	
When landing pilot suddenly opened			,
throttle to prevent propellor going			
dead while brakes on.			
	RECOMMENDATIONS:		
	NIL		
PRIMARY CAUSE:			
ANTERCOMENTATIONS O DEXXOTER PILOT SUDDENLY			
PENED THROTTLE WHILE BRAKES WERE APPLIED.			
	ACTION TAKEN:		
	(A) DISCIPLINARY (B) TECHNICAL (C)	OTHER	
	P/O BROWNING'S LOGBOOK ENDORSED.		
	.,		
SECONDARY CAUSE OR CONTRIBUTING FACTORS:			
Edit at today x your adagen newath a			
ERROR OF JUDGMENT		RECORDED BY	DATE
		CHECKED BY	DATE