

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Routine solo practice.	OR COMMANDING OFFICER'S REPORT: "COURT OF INQUIRY"
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: OCTOBER 20TH, 1941.
Aircraft developed spin from which	COMPOSITION:
student could not recover - student	,,
baile d out approximately one thousa feet and landed safely - aircraft	
crashed.	Member F/O J.T. Arnold (C1442) RECOMMENDATIONS:
	More emphatic instructions that pupils are to
PRIMARY CAUSE:	return to base when they encounter weather such as was encountered by LAC Horan, F.J.
Student unable to maintain equilibron instruments when encountering ad	
on instruments when encountering ad	
	ACTION TAKEN:
on instruments when encountering ad	ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other
on instruments when encountering adweather conditions.	ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other None.
on instruments when encountering adweather conditions. SECONDARY CAUSE OR CONTRIBUTING FACTORS:	ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other None. (None Report Court of Inquiry)
meather conditions. SECONDARY CAUSE OR CONTRIBUTING FACTORS: Incorporience of pilot to be able to recover equilibrium from unusual	ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other None.
on instruments when encountering ad	ACTION TAKEN: (A) Disciplinary (B) Technical (C) Other None. (None Report Court of Inquiry)