

, , , , , , , , , , , , , , , , , , ,	, , , , , , , , , , , , , , , , , , ,)
) DUTY ON WHICH ENGAGED: COURT OF	INQUIRY, INVESTIGATING OFFICER)
Practicing sequences 6,7,9,10,15,17.	ANDING OFFICER'S REPORT:	
) NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE:	, , , ,	
Immediately after making an COMPOSITI	ion: Lada Villa Villa Villa Color)
) apparently successful landing, appli-)
cation of the brakes caused the aircraft to turn up on its nose and break RECOMMEN	NDATIONS.)
the airscrew.	<u>1961 1083.</u>	
PRIMARY CAUSE:)
)
) Harsh application of brakes.		
ACTION TA)
(A) Disci	PLINARY (B) TECHNICAL (C) OTHER)
More do	ual instruction.)
)
) SECONDARY CAUSE OR CONTRIBUTING FACTORS:)
)
Aircraft turned up on its nose.	RECORDED BY DATE)
,	CHECKED BY DATE	
	CHECKED BY DATE)