

<u>,                                    </u>	
) DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
) Taxiing prior to take off.	OR COMMANDING OFFICER'S REPORT:
) NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: R170
) Taxied into obstruction near edg	ge COMPOSITION:
) of field	TCO/PCT
)	•
)	RECOMMENDATIONS:
)	Nil
) PRIMARY CAUSE:	
Insufficient look-out being kept by pilot of aircraft when taxiir	
) >	ACTION TAKEN:
<b>)</b>	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
)	Nil
)	***
)	
) SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
) Taxied into screw picket left in	the
ground within aerodrome boundarie	RECORDED BY
)	CHECKED BY DATE