

	) ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) ) )
DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
) Solo practice.	OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: MOLT
) Tiger Moth 4050 was stopped on runway and Tiger Moth 4064 on	COMPOSITION:
ground (landing ground) looped into it.	DATE: COMPOSITION:  COMPOSITION:  COMPOSITION:  RECOMMENDATIONS:
,	COMMENDATIONS.
) PRIMARY CAUSE:	NIL
) Error in judgment on part of pupil in landing too close to other airc	
)	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  )
	,
)	NIL
)	,
) SECONDARY CAUSE OR CONTRIBUTING FACTORS:	)
) ON LANDING 4064 CRASHED INTO PARKED AIRCRAFT	
) 4050.	RECORDED BY DATE
Ĵ	CHECKED BY DATE )