

ĵ		<b>,,,,,,,,,,,,,,,</b> ,,,,,,,,,,,,,,,,,,,,,
)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
)	Test flight from maintenance.	OR COMMANDING OFFICER'S REPORT:  **TNVKSTIGATING OFFICER'S**
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: 11.12.42 "REPORT"
)	Engine failed and pilot had to	COMPOSITION: FE/HOL/AS/GL/M/I
)	make forced landing from 2500 feet into a small field.	Sqdn Idr. John H. Arbick.
)		RECOMMENDATIONS:
)		)
)		All test flights be carried out within gliding
)	PRIMARY CAUSE:	distance of the Aerodrome.
)	Internal glycol leak causing engine	)
)	to fail.	)
)	Poor judgment on the part of the	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
í	Pilot in that he did not attempt to	
,	land at Trenton Airport when glycol leak was first noticed.	N11
•	leak was lirst noticed.	,
)		)
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:	)
)	Engine ran up temperature melting	RECORDED BY DATE
)	the radiator and the pilot was bline	ded
)	by glycol which forced him to land.	CHECKED BY DATE
)	· · · · · · · · · · · · · · · · · · ·	