

TYPE OF A/C		CAUSES OF ACCIDENTS										MISCELLANEOUS CAUSES													
PILOT		AIRFRAME FAILURE										ENGINE FAILURE													
UNIT 34 S.F.T.S.		COM. 4		PLACE Medicine Hat Aerodrome						DATE 16-12-41		TIME 0145		MISCELLANEOUS CAUSES HAND'D INST'S. WEATHER DRINKS. AL'G SURF. OTHER UN'D/TD PRIMARY TAXING LANDING TAKE-OFF FLIGHT STAFF FATAL INJ. 3RD.											
Medicine Hat		4		Medicine Hat Aerodrome						H.O. FILE 1300-AS205															
A/C TYPE Oxford		No. AS205		CRASH CAT. B		SE		ME X		DAY		NIGHT X		STAGE OF FLIGHT UN'D/TD PRIMARY TAXING LANDING TAKE-OFF FLIGHT STAFF FATAL INJ. 3RD.											
NAME		RANK		No.		DUTY		INJURIES				SERIOUS													
Ayton, J.V.		Sgt		R101269		P.		Uninjured.				FATAL		INJURY											
Stourton,		LAC		1312383		P.P.		Uninjured.																	
												CARD SERIAL NO.													
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS													
Oxford		AS205		Serious								INST.		NIGHT		ON TYPE				TOTAL		LAST 6 MOS.			
Cheetah		A178779		Serious								16		17		317				389		223			
Cheetah		A178847		Serious																					
SIGNAL No. & DATE		UNIT No. & DATE				COM. No. & DATE				REPORT		FILE		DATE											
T 82		17-12-41																							
NATURE OF ACCIDENT																									

DUTY ON WHICH ENGAGED:

Night flying dual

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

HL70

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Aircraft hit obstacle shortly after
night flying take off - airscrews
and undercarriage damaged causing forced
landing on aerodrome.

COMPOSITION:

OCO/PSJ/PCDM

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

Under conditions of no wind use of
hot air intake in warm atmosphere did
not give sufficient power to clear
obstacle at end of take off run.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Carburettor heater controls in COLD for all take
offs and occasions when full power is needed except
if icing conditions are evident.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Aircraft crash landed with damaged
airscrews and undercarriage.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____