

```
DUTY ON WHICH ENGAGED:
                                     COURT OF INQUIRY, INVESTIGATING OFFICER
  Landing practice.
                                     OR COMMANDING OFFICER'S REPORT:
 NATURE OF ACCIDENT AND STAGE OF FLIGHT:
                                     DATE:
  Aircraft 4166 collided with 4160
                                     COMPOSITION:
  after landing.
                 LAC McAmulty, carried
out a landing in the near proximity of the
aircraft pileted by LAC Bull, and was
unable to check the forward speed in RECOMMENDATIONS:
sufficient time to avaid his aircraft
from colliding.
                                      W17
 PRIMARY CAUSE:
 Carried out landing in the close
 proximity of another aircraft.
                                     ACTION TAKEN:
                                       (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
                                      Instructors to impress more freely importance of
                                     landing 50 yards to the right of aircraft that have
                                     landed.
 SECONDARY CAUSE OR CONTRIBUTING FACTORS:
Unable to check forward speed in
                                                                 RECORDED BY
sufficient time to avoid collision.
                                                                 CHECKED BY
                                                                                    DATE
```