

DUTY ON WHICH ENGAGED:

Starting engine.

COURT OF INQUIRY. INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

RL70

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

LAC Crosbie started 5081 without assistance - aircraft moved forward colliding with 4056

DATE:

COMPOSITION:

~~TCR/POM~~
MULT
TCR/POM
MA/XA

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

Disobedience of orders - airman placed on charge.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Airman placed on charge.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Aircraft collided with 4056

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____