A/C		PILOT	OTHERS		Α	RFRAN	E	FAIL	URE			A Part	COLIGN				
PE OF A	UNIT 1 E.F. T.S. COM.					PLACE Malton Aerodi				rome			DATE 19-12-)41TIME 1110 H.O. FILE 1100-43-79				1 145/24
Ļ	A/C TYPE Tiger Moth			·	No. 4379			CRASH CAT.	AT. Cl			M E	D	X_			
					LAC		\rightarrow	P.	Uninj				FATAL IN		INTURY	S P P	
ENGINE											CARD SERIAL NO				S OFF OFF OFF OFF OFF OFF OFF OFF OFF OF		
PE OF E	L																1 1 1/3/2
ΤY		& ENGINE NO. OF DAMA		EXTENT OF DAMAG		PORT SERI		DAT	E INST NIGHT						TOTAL LAST		T A CHALLE
7	F	T. Motl	4379	Slight Nil					-				:10	16	:10		O T TUEST
CATEGORY	SIGNAL NO. & DATE UNIT NO. & DA				DATE	TE COM. No. &			ATE	TE REPOR		₹Т	T FILE		DATE		
/	_				N.	ATURE	,	0 F	ACC	CID	ENT	· , , ,	n ² /2 ³ /	/. /	15/26	1/2 /20	9/3º/3º xx

```
DUTY ON WHICH ENGAGED:
                                    COURT OF INQUIRY, INVESTIGATING OFFICER
First solo flight.
                                    OR COMMANDING OFFICER'S REPORT:
                                                                  R170
NATURE OF ACCIDENT AND STAGE OF FLIGHT:
                                    DATE:
Sent on first solo flight by
                                                     10/850
                                    COMPOSITION:
assistant chief flying instructor
after solo flight test - undershot
on approach to land and did not use
throttle, landing with right lower RECOMMENDATIONS:
wing on boundary cone marker, break-
                                       Nil
ing rear spar.
PRIMARY CAUSE:
Carelessness in that throttle was
not used when aircraft undershot after
being instructed just prior to accident.
                                     (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
                                      Paraded. Medically checked, negative report.
                                      Awarded Tadays C.B. Flying training discontinued
                                      shortly after.
SECONDARY CAUSE OR CONTRIBUTING FACTORS:
 Right wing of aircraft struck boundary cone
                                                               RECORDED BY
on landing breaking rear spar.
                                                               CHECKED BY
                                                                                   DATE
```