

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER Investigating Officer's
Flying back to Oshawa.	OR COMMANDING OFFICER'S REPORT: R170 Report
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: 28-12-41 / 10/35 J
Struck tree taking off on small	COMPOSITION:
field. Accident was caused by stalling after hitting knoll. A/Com-	F.O. F.H.A. McNeil (J3099) No.20 E.F.T.S. Oshawa
was prematurely airborne. Pilot decided to climb over trees but	RECOMMENDATIONS:
port wing hit small trees rolled and dove to the ground. PRIMARY CAUSE:	Greater margin of safety where it is attempted to fl an a/clout of forced landing where any doubt exists on the practicability, attempt should be discontinue
Aircraft hit knoll in taking off	
from small field. Insufficient	
	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
from small field. Insufficient flying speed to enable pilot to	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER NIL CONCLUSION OF A. I.B.
from small field. Insufficient flying speed to enable pilot to	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER NIL CONCLUSION OF A. L. B. AIRCRAFT STRUCK TREES ON TAKE-OFF DUE TO INSUFFICIENT FLYING SPEED, CAUSED BY WHEELS STRIKING KNOLL SHORTLY AFTER BEING AIR PARME.
from small field. Insufficient flying speed to enable pilot to	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER NIL CONCLUSION OF A. I. B. AIRCRAFT STRUCK TREES ON TAKE-OFF DUE TO INSUFFICIENT FLYING SPEED, CAUSED BY WHEELS STRIKING KNOLL SHORTLY AFTER BEING AIR BORNE. THE PILOT, THE CHIEF ENGINEER AND MANAGER OF THE CIVILIAN OPERATING COMPANY, ALL ERRED IN JUDGMENT IN ATTEMPTING TO TAKE-OFF FROM
from small field. Insufficient flying speed to enable pilot to	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER NIL CONCLUSION OF A.I.B. AIRCRAFT STRUCK TREES ON TAKE-OFF DUE TO INSUFFICIENT FLYING SPEED, CAUSED BY WHEELS STRIKING KNOLL SHORTLY AFTER BEING AIR BORNE. THE PILOT, THE CHIEF ENGINEER AND MANAGER OF THE CIVILIAN OPERATING
from small field. Insufficient flying speed to enable pilot to avoid obstacles.	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER NIL CONCLUSION OF A. I. B. AIRCRAFT STRUCK TREES ON TAKE-OFF DUE TO INSUFFICIENT FLYING SPEED, CAUSED BY WHEELS STRIKING KNOLL SHORTLY AFTER BEING AIR BORNE. THE PILOT, THE CHIEF ENGINEER AND MANAGER OF THE CIVILIAN OPERATING COMPANY, ALL ERRED IN JUDGMENT IN ATTEMPTING TO TAKE-OFF FROM
from small field. Insufficient flying speed to enable pilot to avoid obstacles. SECONDARY CAUSE OR CONTRIBUTING FACTORS:	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER NIL CONCLUSION OF A. I. B. AIRCRAFT STRUCK TREES ON TAKE-OFF DUE TO INSUFFICIENT FLYING SPEED, CAUSED BY WHEELS STRIKING KNOLL SHORTLY AFTER BEING AIR BORNE. THE PILOT, THE CHIEF ENGINEER AND MANAGER OF THE CIVILIAN OPERATING COMPANY, ALL ERRED IN JUDGMENT IN ATTEMPTING TO TAKE-OFF FROM UNSUITABLE FIELD.