

·	
for D.I. Running up engine to test magnetoss	OR COMMANDING OFFICER'S REPORT: R170
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Aircraft nosed over damaging airscrew.	DATE: COMPOSITION:
	RECOMMENDATIONS:
PRIMARY CAUSE:	Nil
Ingine 2200 R.P.M. Control Column slipped forward.	
24 hosed ones EJA	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
Mosein one,	Starting crews have been given further lectures and are being carefully supervised in starting operations.
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
Alreraft nosed over.	RECORDED BY DATE
	CHECKED BY DATE

1 1