

DUTY ON WHICH ENGAGED:

Night flying practice.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

~~REDACTED~~

R-70

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft taxied into Finch II 4479

DATE:

COMPOSITION:

~~Taxi~~
~~into~~
~~Finch II~~

RECOMMENDATIONS:

Nil

TCA/X-M
TCA/X-M

PRIMARY CAUSE:

~~Failure of lights on Finch II 4479~~

9. Collision

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Attention of all pilots brought to orders and emergency procedure when night flying. Asst. control Officer posted permanently while night flying is being carried at taxi post.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Collision of two aircraft.

RECORDED BY

DATE

CHECKED BY

DATE